University of Windsor

Facility Services

NOTICE OF SERVICE INTERRUPTION/WORK FORM

Date of Request (yyyy/mm/dd): 2016-12-19 **Requester**: Rajeev Chawla

Start Date – End

Start Date (yyyy/mm/dd) 2016-12-21 Time (s) 5pm-10pm
End Date (yyyy/mm/dd) 2016-12-21 Time (s) 5pm-10pm

Notes To replace the two ceiling tiles that are stained. Asbestos precaution required.

Building(s) Affected: **1:** Lambton Tower LAM **2:** Please Select
3: Please Sele **4:** Please Select

Areas/Rooms Affected: 3120

Service to be interrupted: **1:** HVAC **2:** Access to the lab
3: **4:**

Description/Reason for Project:

Replace the two stained ceiling tiles near the exhaust grill. Asbestos precautions to be taken.

Contractor: Spectrum Contracting **Phone #:** (519) 974-0484

Contractor/Project Managers: Randy/Ray **Phone #:**

Should you have any questions or concerns, please contact

Rajeev Chawla, Manager, Maintenance at 519-253-3000 ext. 2854

Notes:

ECC to turn fans off at 5:00 pm to the area serving Lab in room 3120 Lambton Tower. Contractor to inform ECC when work is completed so that the fans can be turned back on.